

# Raw Brass Stampings Contd

E21

## Drops and Shapes Contd:



970 4R



6001



3905



2548



5356



3881



4394



8460



0295



1018



1016



1017



0307



0303



0305




0308



306



304



5763



5961



5467



0032



5766



5791



5784



5473



1555D



5722



1703



8449



2469D



2469A

Note: D = Dapped (Raised)

0 10 20 30 40 50mm