

# Raw Brass Stampings Contd

E28

## Drops and Shapes:



4822



3252



10545



3178



1056



2318



6378L



6378R




8635



4584



0466



5762




5351



6559



8534



8




3431



4



4



3430

0 10 20 30 40 50mm