


Raw Brass Stampings Contd

E18

Drops and Shapes Contd:



2412



3443



7534



7535



4448



1558



6933



6378L



6378R



2408



1588A



1457



2003



1095




7003
W/RING OR
W/OUT RING



6454




2367



4960




064




001




203



0250
0250 1R




035



6635



6855



6944



0787




787



5592



0894A



3449

0 10 20 30 40 50mm